

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

General Information		
Culvert Site ID:	CV6	Crew: DG + BK
HWY CL STA:		Date: 8/26/03
Plan Sheet:		Time: 1500

Field Inspection Summary			Comments:	
Migration Barrier:	yes	no		uncertain
Maintenance:	yes	no		uncertain
Repair:	yes	no		uncertain
Retrofit:	yes	no		uncertain

Check List for Completed Monitoring Tasks			Comments:
Narrative:	yes	no	
Photographs:	yes	no	
Photo Log:	yes	no	
Velocity Measurements:	yes	no	
Flow Depth Measurements:	yes	no	
Pebble Counts:	yes	no	

Culvert Inlet and Upstream Channel		
1	Sediment deposition	5 ft deposit @ inlet
2	Debris accumulation	none
3	Percent inlet blockage	0
4	Pebble count in channel	-
5	Inlet crown to bed height	3.1
6	Inlet bed elevation	
7	Inlet drop height	0
8	High water marks	2.8 @ culvert inlet
9	Resting pools	backwater areas
10	Condition of inlet	as built
11	Condition of wing walls	n/a
12	Condition of embankment	as built
13	Condition of riprap	"
14	Condition of streambed	" w/ additional riffle
15	Condition of stream banks	w/ vegetated / stable
15	Approach channel flow depth	.2'
16	Flow depth at inlet	<.1'
17	Approach channel velocity	
18	Velocity at inlet	
19	Streambed width	3.5'

Comments:	too shallow for velocity measurements, near 0 juvenile fish throughout inlet channel channel full of silt, no high flow events apparently
profile	0 - 3.1 20-34 50-32 80 3.2 30-30 60-30 90 3.15 10 - 3.4 40-31 70-31 100 3.3

CV6 #2

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

Culvert Barrel and Bed Sediment	
20	Sediment deposition <i>some silt沉积</i>
21	Sediment size <i>gravel/sand as built</i>
22	Bed forms <i>none</i>
23	Resting pools <i>none</i>
24	Crown to bed height
25	% change from as-builtts <i>none - except no bed material placed at bank</i>
26	Flow depth
27	Velocity, trial 1
28	Velocity, trial 2
29	High water marks
30	Debris accumulation <i>no</i>
31	Condition of barrel <i>as built</i>
32	Condition of baffles/weirs <i>n/a</i>
Comments: too small for most measurements, backwatered by Kluane A lot about to inlet	

Culvert Outlet and Downstream Channel	
33	Outlet velocity
34	High water marks
35	Scour hole length
36	Scour hole width
37	Maximum pool depth
38	Distance to maximum pool depth
39	Culvert invert elevation
40	Pool tail crest elevation
41	Invert-to-pool drop
42	Condition of outlet
43	Condition of embankment
44	Condition of pipe bedding
45	Condition of riprap
46	Condition of downstream weir
47	Condition of stream banks
48	Condition of streambed
Comments: Culvert outlet directly into Kluane rd. Culvert backwatered at present water level. No outlet channel	

Fish	
49	Presence/Absence of Fish
Comments: Fish throughout approach channel	

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form**General Information**

Culvert Site ID:	<i>CV 7</i>	Crew:	<i>D G + BK</i>
HWY CL STA:		Date:	<i>8/26/03</i>
Plan Sheet:		Time:	

Field Inspection Summary

Migration Barrier:	yes	no	uncertain
Maintenance:	yes	no	uncertain
Repair:	yes	no	uncertain
Retrofit:	yes	no	uncertain

Comments:

Check List for Completed Monitoring Tasks

Narrative:	yes	no
Photographs:	yes	no
Photo Log:	yes	no
Velocity Measurements:	yes	no
Flow Depth Measurements:	yes	no
Pebble Counts:	yes	no

Comments:

Culvert Inlet and Upstream Channel

1	Sediment deposition	<i>some silt being deposited near inlet</i>
2	Debris accumulation	<i>none</i>
3	Percent inlet blockage	<i>0</i>
4	Pebble count in channel	<i>-</i>
5	Inlet crown to bed height	<i>7.7'</i>
6	Inlet bed elevation	
7	Inlet drop height	<i>0</i>
8	High water marks	<i>6.1' & inlet erosion</i>
9	Resting pools	<i>buck water areas near east shore</i>
10	Condition of inlet	<i>as built</i>
11	Condition of wing walls	<i>"</i>
12	Condition of embankment	<i>"</i>
13	Condition of riprap	<i>"</i>
14	Condition of streambed	<i>"</i>
15	Condition of stream banks	<i>"</i>
15	Approach channel flow depth	<i>.9'</i>
16	Flow depth at inlet	<i>1.0</i>
17	Approach channel velocity	<i>98 cm Piggy meter</i>
18	Velocity at inlet	<i>102</i>
19	Streambed width	<i>30'</i>

Comments: *little change since constructed. Some willows growing in west bank but 1.4% else & very small*

<i>profile</i>	<i>0 - 7.7'</i>	<i>20 - 7.3</i>	<i>50 - 9.0</i>	<i>80 - 8.4</i>
		<i>30 - 7.3</i>	<i>60 - 8.8</i>	<i>90 - 8.5</i>
	<i>10 - 7.9</i>			
		<i>40 - 7.8</i>	<i>70 - 7.9</i>	<i>100 - 8.9</i>

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

Culvert Barrel and Bed Sediment	
20	Sediment deposition <i>none</i>
21	Sediment size <i>large cobbles, boulders</i>
22	Bed forms <i>none</i>
23	Resting pools <i>none</i>
24	Crown to bed height <i>8.5'</i>
25	% change from as-built
26	Flow depth <i>2.35'</i>
27	Velocity, trial 1 <i>92 on Pymay</i>
28	Velocity, trial 2
29	High water marks
30	Debris accumulation <i>none</i>
31	Condition of barrel <i>good</i>
32	Condition of baffles/weirs <i>good</i>
Comments: Bare spot remains in culvert bottom. Almost no deposition has occurred in culvert. Large boulders help at constricts. <i>adult DV noted in culvert</i>	

Culvert Outlet and Downstream Channel	
33	Outlet velocity <i>116 on Pymay</i>
34	High water marks
35	Scour hole length <i>33'</i>
36	Scour hole width <i>33'</i>
37	Maximum pool depth <i>2.6'</i>
38	Distance to maximum pool depth <i>175'</i>
39	Culvert invert elevation
40	Pool tail crest elevation <i>8.3' ↓ culvert invert</i>
41	Invert-to-pool drop
42	Condition of outlet <i>as built</i>
43	Condition of embankment <i>as built</i>
44	Condition of pipe bedding <i>as built</i>
45	Condition of riprap <i>as built</i>
46	Condition of downstream weir <i>good with fish passage</i>
47	Condition of stream banks <i>no vegetation</i>
48	Condition of streambed <i>as built</i>
Comments: School of DV in adult pool. No signs of outlet pool being over-tipped Functioning as designed, except outlet channel likely needs work.	

Fish	
49	Presence/Absence of Fish
Comments:	

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

General Information

Culvert Site ID:	CV 8	Crew:	DG + BK
HWY CL STA:		Date:	8/26/03
Plan Sheet:		Time:	1215

Field Inspection Summary

Migration Barrier:	yes	<input checked="" type="checkbox"/>	uncertain
Maintenance:	yes	<input checked="" type="checkbox"/>	uncertain
Repair:	yes	<input checked="" type="checkbox"/>	uncertain
Retrofit:	yes	<input checked="" type="checkbox"/>	uncertain

Comments:

Agrees w/ ha. 14

Check List for Completed Monitoring Tasks

Narrative:	<input checked="" type="checkbox"/>	yes	no
Photographs:	<input checked="" type="checkbox"/>	yes	no
Photo Log:	<input checked="" type="checkbox"/>	yes	no
Velocity Measurements:	<input checked="" type="checkbox"/>	yes	no
Flow Depth Measurements:	<input checked="" type="checkbox"/>	yes	no
Pebble Counts:	<input checked="" type="checkbox"/>	yes	<input checked="" type="checkbox"/>

Comments:

Peggy meter

no barrel measurements, too small

Culvert Inlet and Upstream Channel

1	Sediment deposition	some silt accumulation
2	Debris accumulation	small amount of debris accumulation
3	Percent inlet blockage	0
4	Pebble count in channel	-
5	Inlet crown to bed height	3.45
6	Inlet bed elevation	
7	Inlet drop height	0
8	High water marks	none
9	Resting pools	backwater at inlet
10	Condition of inlet	as built
11	Condition of wing walls	n/a
12	Condition of embankment	as built
13	Condition of riprap	"
14	Condition of streambed	
15	Condition of stream banks	vegetated
16	Approach channel flow depth	2'
17	Flow depth at inlet	3'
18	Approach channel velocity	60 clicks Peggy meter
19	Velocity at inlet	27 clicks Peggy meter

Comments:

low flow, silt accumulating @ inlet, banks becoming well vegetated
juvenile fish noted

profile 0-3.45	20-3.3	40-2.9	70-2.0	100-1.9
10 3.5	30-3.2	50 2.3	80-2.1	
		60 2.1	90 2.2	

Culvert Evaluation Field Form

Culvert Barrel and Bed Sediment	
20	Sediment deposition <i>silt deposited on bed</i>
21	Sediment size <i>silt/gravel/cobble</i>
22	Bed forms <i>bank</i>
23	Resting pools <i>back water in lower culvert</i>
24	Crown to bed height
25	% change from as-builts <i>0</i>
26	Flow depth
27	Velocity, trial 1
28	Velocity, trial 2
29	High water marks <i>none</i>
30	Debris accumulation <i>none</i>
31	Condition of barrel <i>as built</i>
32	Condition of baffles/weirs <i>n/a</i>
Comments: Too small for interior measurements. Backwatered in lower $\frac{1}{3}$	

Culvert Outlet and Downstream Channel					
33	Outlet velocity <i>5 on Hwy</i>				
34	High water marks <i>none</i>				
35	Scour hole length <i>none</i>				
36	Scour hole width <i>-</i>				
37	Maximum pool depth <i>-</i>				
38	Distance to maximum pool depth <i>-</i>				
39	Culvert invert elevation				
40	Pool tail crest elevation <i>-</i>				
41	Invert-to-pool drop <i>-</i>				
42	Condition of outlet <i>as built</i>				
43	Condition of embankment <i>some veg mixed w/ rock</i>				
44	Condition of pipe bedding <i>as built</i>				
45	Condition of riprap <i>as built</i>				
46	Condition of downstream weir <i>n/a</i>				
47	Condition of stream banks <i>mostly vegetated</i>				
48	Condition of streambed				
Comments: water is backed up into culvert no fish noted					
profile	0 - 3.3	20 - 3.5	50 - 3.0	80 - 3.2	lower channel very
		30 - 3.3	40 - 3.15	70 - 3.0	silted in, current relevant
	10 3.6	40 - 3.2	70 - 3.9	100 - 3.0	just below profile

Fish	
49	Presence/Absence of Fish
Comments: Very few fish noted	

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

General Information	
Culvert Site ID:	CV 9
HWY CL STA:	Crew: DG + BK
Plan Sheet:	Date: 8/28/03
	Time: 1515

Field Inspection Summary			Comments:
Migration Barrier:	yes <input checked="" type="checkbox"/>	uncertain <input type="checkbox"/>	
Maintenance:	yes <input checked="" type="checkbox"/>	uncertain <input type="checkbox"/>	
Repair:	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>	
Retrofit:	yes <input checked="" type="checkbox"/>	uncertain <input type="checkbox"/>	

Check List for Completed Monitoring Tasks			Comments:
Narrative:	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>	
Photographs:	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>	
Photo Log:	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>	
Velocity Measurements:	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>	
Flow Depth Measurements:	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>	
Pebble Counts:	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>	

Culvert Inlet and Upstream Channel		
1	Sediment deposition	none
2	Debris accumulation	"
3	Percent inlet blockage	none
4	Pebble count in channel	
5	Inlet crown to bed height	7.8'
6	Inlet bed elevation	
7	Inlet drop height	none
8	High water marks	5.9' & culvert inlet
9	Resting pools	near LWD
10	Condition of inlet	good
11	Condition of wing walls	n/a
12	Condition of embankment	as built
13	Condition of riprap	"
14	Condition of streambed	good
15	Condition of stream banks	RR is riprap - no vegetation
16	Approach channel flow depth	0.6'
17	Flow depth at inlet	2.6' 198 on Pygmy
18	Approach channel velocity	5 sec - 20'
19	Velocity at inlet	5 sec - 20'
	Streambed width	20.0'

Comments:
no fish noted Incorporate vegetation into stream banks

profile
 0 - 7.8 20.74 50 65 80 61
 10 7.75 30 7.4 60 6.35 90 6.7
 10 7.75 40 7.2 70 5.65 100 8.2



Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

Culvert Barrel and Bed Sediment	
20	Sediment deposition <i>none</i>
21	Sediment size <i>gravel / cobble</i>
22	Bed forms <i>none</i>
23	Resting pools <i>none</i>
24	Crown to bed height
25	% change from as-built
26	Flow depth <i>.85'</i>
27	Velocity, trial 1 <i>156 on Peggay</i>
28	Velocity, trial 2
29	High water marks
30	Debris accumulation <i>none</i>
31	Condition of barrel <i>good</i>
32	Condition of baffles/weirs <i>n/a</i>
Comments:	
<i>channel complexity would help - near to shore flow</i>	

Culvert Outlet and Downstream Channel	
33	Outlet velocity <i>9 sec / 20' 114 on Peggay</i>
34	High water marks
35	Scour hole length <i>none</i>
36	Scour hole width <i>"</i>
37	Maximum pool depth <i>"</i>
38	Distance to maximum pool depth <i>none</i>
39	Culvert invert elevation
40	Pool tail crest elevation <i>none</i>
41	Invert-to-pool drop <i>none</i>
42	Condition of outlet <i>good</i>
43	Condition of embankment <i>stable</i>
44	Condition of pipe bedding <i>"</i>
45	Condition of riprap <i>"</i>
46	Condition of downstream weir <i>"</i>
47	Condition of stream banks <i>riparian near culvert</i>
48	Condition of streambed <i>good</i>
Comments:	
<i>downstream area seems to have little effect of this culvert profile</i>	
<i>profile</i>	<i>20 - 8.45 50 8.15 80 8.1</i>
<i>0 - 8.45</i>	<i>30 9.7 60 7.7 90 8.0</i>
<i>10 - 8.85</i>	<i>40 8.4 70 8.15 100 8.4</i>

Fish	
49	Presence/Absence of Fish <i>N</i>
Comments:	
<i>no fish noted</i>	

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

General Information		
Culvert Site ID:	CV10	Crew: DG + BK
HWY CL STA:		Date: 8/25/07
Plan Sheet:	Time:	

Field Inspection Summary		
Migration Barrier:	yes	no
Maintenance:	yes	no
Repair:	yes	no
Retrofit:	yes	no
Comments: very low flow, impeding fish passage		

Check List for Completed Monitoring Tasks		
Narrative:	yes	no
Photographs:	yes	no
Photo Log:	yes	no
Velocity Measurements:	yes	no
Flow Depth Measurements:	yes	no
Pebble Counts:	yes	no
Comments:		

Culvert Inlet and Upstream Channel		
1	Sediment deposition	no - algae growth
2	Debris accumulation	n/a
3	Percent inlet blockage	0
4	Pebble count in channel	-
5	Inlet crown to bed height	3.0
6	Inlet bed elevation	
7	Inlet drop height	n/a
8	High water marks	
9	Resting pools	none
10	Condition of inlet	good
11	Condition of wing walls	n/a
12	Condition of embankment	as bank
13	Condition of riprap	as bank
14	Condition of streambed	
15	Condition of stream banks	vegetated
15	Approach channel flow depth	0.1'
16	Flow depth at inlet	0.1'
17	Approach channel velocity	too shallow
18	Velocity at inlet	
19	Streambed width	2.6' P culvert
Comments:		
profile 0-31 30 1.85 60 10 2.45 40 1.85 20 2.1 50 3.05		
pond/bog at 50' P culvert		

CV10 #2

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

Culvert Barrel and Bed Sediment		
20	Sediment deposition	no
21	Sediment size	gravel/cobbles
22	Bed forms	none
23	Resting pools	culvert backwater
24	Crown to bed height	3-4
25	% change from as-built	
26	Flow depth	
27	Velocity, trial 1	basically 0
28	Velocity, trial 2	
29	High water marks	
30	Debris accumulation	none
31	Condition of barrel	as built
32	Condition of baffles/weirs	n/a
Comments:		
no fish noted		

Culvert Outlet and Downstream Channel			
33	Outlet velocity	0	
34	High water marks		
35	Scour hole length	none	
36	Scour hole width	11	
37	Maximum pool depth	11	
38	Distance to maximum pool depth	none	
39	Culvert invert elevation		
40	Pool tail crest elevation	none	
41	Invert-to-pool drop	none	
42	Condition of outlet	good	
43	Condition of embankment	as built	
44	Condition of pipe bedding	11	
45	Condition of riprap	11	
46	Condition of downstream weir	4/4	
47	Condition of stream banks	good	
48	Condition of streambed	good	
Comments:			
0-3.45	20-3.75	40 3.8 70 4.5	100-5.2
		50 3.95 70 4.7	
10-3.45	70 3.65	60 4.1 70 4.8	

Fish		
49	Presence/Absence of Fish	no fish noted
Comments:		

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

General Information		
Culvert Site ID:	(CV11)	
HWY CL STA:	Crew: DG, BK	
Plan Sheet:	Date: 8/25/07	Time: 1330

Field Inspection Summary		
Migration Barrier:	yes	no
Maintenance:	yes	no
Repair:	yes	no
Retrofit:	yes	no
Comments: no water, no sign of recent flow		

Check List for Completed Monitoring Tasks		
Narrative:	yes	no
Photographs:	yes	no
Photo Log:	yes	no
Velocity Measurements:	yes	no
Flow Depth Measurements:	yes	no
Pebble Counts:	yes	no
Comments:		

Culvert Inlet and Upstream Channel		
1	Sediment deposition	
2	Debris accumulation	
3	Percent inlet blockage	
4	Pebble count in channel	
5	Inlet crown to bed height	6.35
6	Inlet bed elevation	
7	Inlet drop height	
8	High water marks	
9	Resting pools	
10	Condition of inlet	
11	Condition of wing walls	
12	Condition of embankment	
13	Condition of riprap	
14	Condition of streambed	
15	Condition of stream banks	
15	Approach channel flow depth	
16	Flow depth at inlet	
17	Approach channel velocity	
18	Velocity at inlet	
19	Streambed width	

Comments:
no evidence of recent flow

CVA #2

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

Culvert Barrel and Bed Sediment	
20	Sediment deposition
21	Sediment size
22	Bed forms
23	Resting pools
24	Crown to bed height
25	% change from as-builts
26	Flow depth
27	Velocity, trial 1
28	Velocity, trial 2
29	High water marks
30	Debris accumulation
31	Condition of barrel
32	Condition of baffles/weirs
Comments: no recent evidence of flowing water.	

Culvert Outlet and Downstream Channel	
33	Outlet velocity
34	High water marks
35	Scour hole length
36	Scour hole width
37	Maximum pool depth
38	Distance to maximum pool depth
39	Culvert invert elevation
40	Pool tail crest elevation
41	Invert-to-pool drop
42	Condition of outlet
43	Condition of embankment
44	Condition of pipe bedding
45	Condition of riprap
46	Condition of downstream weir
47	Condition of stream banks
48	Condition of streambed
Comments: 6.75' bed to culvert invert	

Fish	
49	Presence/Absence of Fish
Comments:	

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

General Information		
Culvert Site ID:	CV12	
HWY CL STA:	Crew: Gregorich & Kolyntseva	
Plan Sheet:	Date: 8/25/07	Time: 1345

Field Inspection Summary		
Migration Barrier:	<input checked="" type="checkbox"/>	yes
Maintenance:	<input checked="" type="checkbox"/>	no
Repair:	<input type="checkbox"/>	yes
Retrofit:	<input type="checkbox"/>	yes
uncertain		

Comments:
sheet flow thru culvert impeding fish
rock forms over culvert neck passage
regional gravel entering stream

Check List for Completed Monitoring Tasks		
Narrative:	<input type="checkbox"/>	yes
Photographs:	<input type="checkbox"/>	no
Photo Log:	<input type="checkbox"/>	yes
Velocity Measurements:	<input type="checkbox"/>	yes
Flow Depth Measurements:	<input type="checkbox"/>	yes
Pebble Counts:	<input type="checkbox"/>	no

Comments:

Culvert Inlet and Upstream Channel		
1	Sediment deposition	no
2	Debris accumulation	no
3	Percent inlet blockage	none
4	Pebble count in channel	no
5	Inlet crown to bed height	6.25'
6	Inlet bed elevation	
7	Inlet drop height	none
8	High water marks	5.2'
9	Resting pools	over widened channel & culvert formed pool
10	Condition of inlet	as built
11	Condition of wing walls	one support not belted
12	Condition of embankment	as built
13	Condition of riprap	"
14	Condition of streambed	over widened & culvert
15	Condition of stream banks	good
15	Approach channel flow depth	
16	Flow depth at inlet	.6'
17	Approach channel velocity	82 on Dgney
18	Velocity at inlet	19 in "
19	Streambed width	5.5' & culvert in flume

Comments:

Over widened & culvert Rock beam & inlet is only partially effective
silt accumulation on channel margins

juvenile fish noted

page 1 of 2

stream profile culvert invert control point

0 - 6.25	30 - 5.95	60 - 3.9	90 - 4.5
10 - 6.3	40 5.6	70 4.4	100 - 4.0
20 - 6.2	50 6.05	80 3.8	

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

Culvert Barrel and Bed Sediment		
20	Sediment deposition	
21	Sediment size	gravel / cobble
22	Bed forms	none - slight flowing in center
23	Resting pools	some backwater areas
24	Crown to bed height	5.6
25	% change from as-built	
26	Flow depth	~2'
27	Velocity, trial 1	5' in Piggy
28	Velocity, trial 2	
29	High water marks	5' A bed
30	Debris accumulation	none
31	Condition of barrel	as built
32	Condition of baffles/weirs	n/a
Comments:		
no channel, sheet flow. Difficult to get velocity measurement		

Culvert Outlet and Downstream Channel		
33	Outlet velocity	27 sec = 20' 22 - Piggy
34	High water marks	
35	Scour hole length	none
36	Scour hole width	none
37	Maximum pool depth	none
38	Distance to maximum pool depth	n/a
39	Culvert invert elevation	
40	Pool tail crest elevation	n/a
41	Invert-to-pool drop	n/a
42	Condition of outlet	as built
43	Condition of embankment	good
44	Condition of pipe bedding	as built
45	Condition of riprap	n/a
46	Condition of downstream weir	n/a
47	Condition of stream banks	rocky / stable; some willow stalks present
48	Condition of streambed	
Comments:		
		(5.2') Rock bend P outlet can less eff. flow road gravel entering stream
profile	20 1.4	50-7.45 80 7.6
0 - 6.85	30 6.75	60-7.05 80 8.4
10 6.2	40 6.9	70-7.05 100 7.9
		many scours 11' present (coh.)

Fish		
49	Presence/Absence of Fish	4
Comments:		
		juvenile fish noted P + L culvert, none in culvert

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

General Information		
Culvert Site ID: CV-13	Crew: Gregovich, Kirkpatrick	
HWY CL STA:	Date: 8-25-03	
Plan Sheet:	Time: 1143	

Field Inspection Summary		
Migration Barrier:	yes	no
Maintenance:	yes	no
Repair:	yes	no
Retrofit:	yes	no
Comments: Water leaking out of culvert surface at 3rd + 4th bottle from bottom. Water being lost to groundwater.		

Check List for Completed Monitoring Tasks		
Narrative:	yes	no
Photographs:	yes	no
Photo Log:	yes	no
Velocity Measurements:	yes	no
Flow Depth Measurements:	yes	no
Pebble Counts:	yes	no
Comments:		

Culvert Inlet and Upstream Channel		
1	Sediment deposition	gravel bar forming
2	Debris accumulation	no
3	Percent inlet blockage	none
4	Pebble count in channel	4/10
5	Inlet crown to bed height	6'0
6	Inlet bed elevation	
7	Inlet drop height	
8	High water marks	5.8 ft inlet crown
9	Resting pools	25' + culvert
10	Condition of inlet	as built
11	Condition of wing walls	n/a
12	Condition of embankment	good / vegetated
13	Condition of riprap	as built
14	Condition of streambed	aggrading
15	Condition of stream banks	rocky / stable
15	Approach channel flow depth	25'
16	Flow depth at inlet	.25'
17	Approach channel velocity	40 on Pygmy
18	Velocity at inlet	too slow to measure
19	Streambed width	8' + culvert in flume

Comments:
 juvenile noted at inlet gravel bar forming above inlet, high flows appear to be common w/ some backwatering

profile 0 - 6.0'	30 - 5.8	60 5.25	90
10 6.1	40 5.85	70 4.5	100
20 5.55	50 6.0	80 2.9	

CV13 #2

Haines Highway Mitigation Monitoring

Culvert Evaluation Field Form

Culvert Barrel and Bed Sediment	
20	Sediment deposition mostly sand
21	Sediment size gravel / cobble
22	Bed forms no
23	Resting pools behind baffle
24	Crown to bed height 5.95
25	% change from as-built
26	Flow depth -5'
27	Velocity, trial 1
28	Velocity, trial 2
29	High water marks none
30	Debris accumulation none
31	Condition of barrel good
32	Condition of baffles/weirs good
Comments:	
baffles in good shape, water is leaking out of culvert baffles make flow measurements unreliable juvenile fish noted in culvert	

Culvert Outlet and Downstream Channel	
33	Outlet velocity 15 m Pygmy
34	High water marks
35	Scour hole length no scour hole / beam at an angle
36	Scour hole width -
37	Maximum pool depth 5'
38	Distance to maximum pool depth 5'
39	Culvert invert elevation
40	Pool tail crest elevation ~16
41	Invert-to-pool drop
42	Condition of outlet as built
43	Condition of embankment "
44	Condition of pipe bedding "
45	Condition of riprap "
46	Condition of downstream weir "
47	Condition of stream banks rock, stable
48	Condition of streambed rocky, stable
Comments:	
profile 0-6.15 20-6.4 40-7.3 60 7.9 90-8.9 10-6.4 30-6.7 50-7.6 70 8.6 100-9.0	
lot of juvenile fish present (cobs) 80 8.4 surface water ends 0' (cm) fish present	

Fish	
49	Presence/Absence of Fish Present
Comments:	
lot of fish present, especially below culvert	